

# Colour Selector

Manufacturers of Cladding Products for the Construction Industry



## STEADMANS 200LG

#### Coating Performance

Steadmans 200LG is an extremely durable leathergrain Plastisol product suitable for external use on a wide range of industrial, commercial, agricultural, retail and leisure buildings. Steadmans offer a variety of profiles and products produced in 200LG with a predicted life expectancy of up to 40 years.

A warranty of up to 30 years to first maintenance offers confidence and assurance to specifiers and building owners alike.

# Life to first full repainting for Plastisol coated profilesColoursWall ProfilesRoof ProfilesInlandCoastalInlandCoastalGroup 130252520Group 225202015

#### **Technical Support**

Steadmans offers comprehensive technical support to designers and contractors working with Steadmans products and accessories, including:

- Technical brochures, data sheets and CAD details
- Project showcase and case studies
- Design and installation guidance
- Copies of test certificates
- NBS Specifications



# **COLOURS**

#### Standard Colours

Group: 1



Group: 2

Group: 2

#### High Volume Colours

**Colour:** Juniper Green\* 12B29

Group: 2

Colour: Olive Green\*
Code: 12B27
Group: 1

Colour: Slate Blue\*
Code: 18B29
Group: 2

Colour: Goosewing Grey\*

**Code:** 10A05 **Group:** 1

Colour: Merlin Grey\*
Code: 18B25
Group: 1

Colour: Vandyke Brown\*
Code: 08B29

Group: 2

### **Special Order Colours**

Colour: Hollybush Green

**Code:** 14C39 **Group:** 2

Colour: PetraCode: 04D44Group: 2

Colour: TangerineCode: 06E53Group: 2

Colour: SaffronCode: 08E53Group: 2

Colour: Aztec Yellow Code: 10E55 Group: 2

shown are the nearest equivalents. The printed colours shown are for guidance only. For a true representation please obtain an actual metal swatch sample available on request from Steadmans.

The standard colour references

To ensure tonal consistency between components for a single contract material should come from the same production batch and therefore should be placed as one order.


<sup>\*</sup>Also available in Polyester coated finish

# STEADMANS 200LG

#### Benefits

- Multi layer construction
- 200 micron abrasion resistant durable top coat
- Substrate offering good corrosion resistance
- Leathergrain embossment
- Wide choice of colours available
- High performance reverse side backing coat
- Performance warranty up to 30 years





#### **Property Data**

Property	Data	Test
Paint thickness	200μm	EN13523-1
Gloss	15 - 40	EN13523-2
Scratch resistance	> 35N	EN13523-12
Taber abrasion resistance	10 - 15 mg	EN13523-16
Impact strength	18 Joules	EN13523-5
Adhesion	Satisfactory	EN13253-6
Corrosion resistance Salt spray (hours) Humidity (hours)	1000 1000	EN13253-8 EN13253-25
Max.surface temp.	60°C	Mill
Reaction to fire	Class 0	BS476 part 6 & 7
Resistance to fire	Class A	A BS476 part 3

The figures contained in this table are typical properties and do not constitute a specification.

For further information contact Steadmans Technical Department at support@steadmans.co.uk

Other coatings and colours are available from Steadmans. For further details contact Steadmans Sales Department at info@steadmans.co.uk

#### Annual inspection checklist

Item	Action A)	
	Check that the roof is non-fragile. <sup>B)</sup>	
Establish a safe method of work	Check that the safety equipment is tested in accordance BS EN 795 (including safety lines)	
Leaks, inspect from inside for location	Repair as soon as possible and do not leave until annual maintenance.	
Damage or decay	Repair or replace as necessary.	
Accumulated debris, e.g. trapped leaves or pine needles	Clean away.	
Gutters and drain pipes clean, and free draining	Clean out.	
Gutter joints defective sealant or loose bolts	Repair.	
Loose ridge or other flashings	Repair.	
Missing foam fillers or evidence of damage by birds	Replace.	
Staining caused by ponding or water	Seek advice from a roofing specialist.	
Discoloured areas of the surface coating	Inspect the surface coating and attend to any peeling corrosion or other evident deterioration, as necessary.	
Discoloured areas around fume extract ducts should be closely inspected	Re-coat without delay where attack of the coating has occurred.	
Dirty rooflights	Clean to maintain light transmission.	
Evidence of access to the roof e.g. for maintenance of ventilators	Touch-up any scratches in coating.	
Missing/faded colour caps from fasteners	Replace.	
Missing fasteners	Investigate and replace.	
Corroded or degraded fastener (including sealing element)	Seek advice on replacement.	
Loose fasteners, e.g. where the washer is not in contact the sheet	Tighten only fasteners that are loose. Investigate the cause.	
Sealants visible on roof surface	Seek advice on replacement and suitability of the sealant.	

<sup>&</sup>lt;sup>A)</sup> Where any defects are discovered, these should be reported to the client. Some of these items might be covered by a product/system guarantee. which should be pursued via the contractual chain.

<sup>&</sup>lt;sup>B)</sup> See ACR[M]001 "Red Book" [N1]. ACR[CP]001:2014 "Orange Book" [1] for further guidance on non-fragile roofs (Recommended practice for work on profile sheeted roof) and ACR[CP]002 (Guidance Note for Safe Working on Fragile Roofs, otherwise known as the "Green Book" [30]).

England & Wales	Scotland & Ireland	Scotland
A Steadman & Son	A Steadman & Son	A Steadman & Son
Warnell	Unit C	Mill of Crichie
Welton	Coalburn Road	Fyvie
Carlisle	Fallside Ind Est	Turriff
Cumbria	Bothwell	Aberdeenshire
CA5 7HH	G71 8DA	AB53 8QL
Tel: 016974 78277	Tel: 01698 819 050	Tel: 01651 891 668
Fax: 016974 78530	Fax: 01698 801 764	Fax: 01651 891 698

E-mail: info@steadmans.co.uk Online: www.steadmans.co.uk

